Regency
the first name in solid state

PROFESSIONAL
2 WAY action radio

DATE 3/27/81

SSC Service Bulletin

no. 81-197

TO: ALL REGENCY COMMUNICATIONS PROFESSIONAL SALES & SERVICE CENTERS
ALL REGENCY COMMUNICATIONS PROFESSIONAL SALES REPRESENTATIVES

MODELS AFFECTED: MCU 15, 18, 31, 34; MCBU 19, 35; MICRO COM 01, MICRO COM 04; MICRO COM U01R; MICRO COM U15R

PROBLEM: SQUELCH OPENS ON SOME RADIOS AT COLD TEMPERATURES

CURE: CHANGE C234 TO REGENCY PART NO. 1501-0103-010

NOTE: The value of C234 has not been changed, only the temperature characteristics. The value remains at .01mf.

TECHNICAL SERVICE DEPARTMENT

REGENCY COMMUNICATIONS, INC.